



NOTES:

1. METER BOX LID SHALL BE LABELED SEWER OR BE PLAIN WITH NO LABELING.
2. WIRE BRUSH PIPE AND REMOVE ANY OIL, GREASE OR OTHER DEBRIS PRIOR TO PAINTING.
3. APPLY A MINIMUM OF TWO COATS OF SAFETY YELLOW PAINT IN ACCORDANCE WITH THE APPROVED PRODUCTS LIST.

<b>AUGUSTA COUNTY SERVICE AUTHORITY VERONA, VIRGINIA</b>	
SCALE: NTS	DRAWN BY: ACSA
DATE: FEB. 2005	REVISED: FEB. 2021
<b>MANHOLE VENTILATION</b>	
DRAWING NUMBER: S-8	PAGE: 1 OF 1